VANTAGE

Multi-Discipline Supports

User Bulletin



MDS11.6.sp3.2

Issue 25092006 Rev 0

NOTE:

AVEVA Solutions has a policy of continuing product development: therefore, the information contained in this document may be subject to change without notice.

AVEVA SOLUTIONS MAKES NO WARRANTY OF ANY KIND WITH REGARD TO THIS DOCUMENT, INCLUDING BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE.

While every effort has been made to verify the accuracy of this document, AVEVA Solutions shall not be liable for errors contained herein or direct, indirect, special, incidental or consequential damages in connection with the furnishing, performance or use of this material.

This manual provides documentation relating to products to which you may not have access or which may not be licensed to you. For further information on which Products are licensed to you, refer to your license conditions.

© Copyright 1991 through 2006 AVEVA Solutions Limited

All rights reserved. No part of this document may be reproduced, stored in a retrieval system or transmitted, in any form or by any means, electronic, mechanical, photocopying, recording or otherwise, without prior written permission of AVEVA Solutions.

The software programs described in this document are confidential information and proprietary products of AVEVA Solutions or its licensors.

For details of AVEVA's worldwide sales and support offices, see our website at:
http://www.aveva.com

Contents

1 Introduction 1

2 Changes 2

3 Upgrading from previous releases 4

1 Introduction

This bulletin describes the MDS fault corrections included in the MDS11.6 sp3.2 release.

The MDS11.6.SP3.2 release is a maintenance/partial release, but it does include all data/files released at the previous release, i.e. MDS11.6.SP3.1

The MDS11.6.SP3.2 release needs to be loaded into the existing MDS11.6 .SP3 release directory, which may or may not have had the MDS11.6.SP3.1 release loaded into it.

2 Changes

MDS11.6 sp3.2 is a maintenance/partial release only.

This release includes the following MDS fault corrections shown below.

REMEDY Call Reference No.	*Description of MDS fault*	*MDS PML file names modified*
HPD0033223	**Not selecting a MDS Zone on the Default Creation Zone form, the MDS DESIGN Application Entry Form, and click Cancel, an error occurs, i.e. "Can not find form CDSYTEM".** **However Selecting a Zone and then clicking OK, and then call the form up again and click Cancel the error is not reproduced.**	**mdscanceldflt.pmlfnc**
HPD0033192	**Error raised (2,751) Variable !DIR does not exist.** **Corrected the error by testing the arrive/leave direction of the ELBO to which a TT14 type trunnion may be added.** **Corrected the value calculated in DESPAR num2 of the trunnion type TT14 "MAKEUP" component to ensure the correct length of extra pipe material is added to the Piping Isometric MTO**	**mdssetdattt14.pmlfnc** **mdsmodoffset.pmlfnc**
HPD0033301	**Corrected errors when trying to create a MDS Hanger**	**mdshang.pmlobj** **mdsreoatta.pmlfnc**
HPD0033306	**Extra functionality added to enable the MDS ATTA orientation, stored in the STEX attribute, to be output WRT SITE etc… on the Piping Isometric** **An additional KEYWORD and the required WRT SETTING needs to be added to the PDMS project's DES-SUPP-DEFS default file, e.g.** **MDSORIWRT SITE or** **MDSORIWRT WORLD** ***** IMPORTANT NOTE ***** **The default MDS ATTA orientation will still be output WRT WORLD if no changes are made to the DES-SUPP-DEFS default file.**	**mdstransport.pmlfnc**

REMEDY Call Reference No.	*Description of MDS fault*	*MDS PML file names modified*
HPD0033107	**Correction of a MDS DESIGN application graphical view navigation fault**	**edgcntrl.pmlobj** **gphviews.pmlobj**

3 Upgrading from previous releases

- No upgrade procedure is necessary for the MDS11.6 sp3.2 release.

End of document